## Oil Field Environmental Incident Summary

**Responsible Party:** HESS CORPORATION **Well Operator:** HESS CORPORATION

Well Name: TMU M-143 (RICE)CTB

Field Name: N/A Well File #:

Date Incident: 3/16/2014 Time Incident: 13:00 Facility ID Number: 400032-11

County: MOUNTRAIL Twp: 158 Rng: 94 Sec: 18 Qtr:

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16TH ST SW STE 20

MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.2 MileDistance Nearest Water Well:0.2 Mile

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

1 Barrels 0.5 Barrels 0.88 barrels

Brine Other

Oil

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 5/12/2015 Clean Up Concluded: 4/21/2014

Risk Evaluation:

N/A

Areal Extent:

16 feet by 25 feet, on the facility location

## Potential Environmental Impacts:

The release occurred aboveground, and the released crude oil remained on the facility location. Absorbent pads were utilized to recover the crude oil from the floor of the treater building. The impacted material outside the northeast wall of the treater building will be excavated, stockpiled, and

## Action Taken or Planned:

The release occurred aboveground, and the released crude oil remained on the facility location. Absorbent pads were utilized to recover the crude oil from the floor of the treater building. The impacted material outside the northeast wall of the treater building will be excavated, stockpiled, and transported off-site to a properly permitted facility for disposal.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

## **Updates**

Date: 5/12/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release from a pump leak remained on location according to the report. NDIC retains oversight.